

# Interim Reclamation and Stormwater Inspection

October 11, 2023

Operator: CCRP OPERATING INC - #10665

Location ID: 443490

Inspection Document #: 697504900

Weld County, CO

Chris Binschus  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Meader 5-N Pad  
Location ID: 443490



**Photo 1.** Photo taken from the location, facing West. Photo illustrates interim reclamation has been performed and perennial vegetation was observed and meets Rule 1003 standards.



**Photo 2.** Photo taken from the location, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: Meader 5-N Pad  
Location ID: 443490



**Photo 3.** Photo taken from the southeastern interim area, facing West. See comments under Photo 1.



**Photo 4.** Photo taken from the southern interim area, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: Meader 5-N Pad  
Location ID: 443490



**Photo 5.** Photo taken from the western interim reclamation area, facing West. Photo illustrates unused equipment (ECD) that needs to be removed.



**Photo 6.** Photo taken from the secondary containment area. Photo illustrates stained soil that needs to be cleaned up and removed. Also, load out lines were observed being stored inside secondary containment. This would be considered unused equipment.

Note- Operator has a load out line hanger located outside of the eastern secondary containment that should be used.