

# Inspection Photos

API: 061-06234

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 10/23/2023



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east toward the location. There is a fence installed around the equipment.



## Inspection Photos



**Photo 2.** Facing southeast toward the tank battery. The secondary containment has been built up higher.



## Inspection Photos



**Photo 3.** Facing east toward the meter run.



## Inspection Photos



**Photo 4.** Facing toward the wellhead.

