

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2023

Submitted Date:

10/27/2023

Document Number:

710500064

FIELD INSPECTION FORMLoc ID 324505 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Newville, Toni		toni_newville@oxy.com	OXY Sheep Mountain Inspections
OXY, COGCC		COGCCInspections@Oxy.co	OXY Sheep Mountain Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211864	WELL	SI	08/01/2020	GW	055-06102	SHEEP MOUNTAIN UNIT 12-2-E	EI
324505	LOCATION	AC			-	SHEEP MOUNTAIN UNIT-628S70W 2NENE	EI

General Comment:

This is an Environmental Inspection for the Sheep Mountain Unit 12-2-E; Location # 324505, active well location located in Huerfano County, Co.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>211864</u>	Type: <u>WELL</u>	API Number: <u>055-06102</u>	Status: <u>SI</u>	Insp. Status: <u>EI</u>
Facility ID: <u>324505</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: The SMU 12-2-E location is under an open Remediation #24088 for Plugging and Abandonment of the well bore. At the time of inspection, the trench surrounding the well bore had recently been partially backfilled with new material. Operator shall assure soils in remediation area are compliant with Table 915-1 standards.

Corrective Action: Per Rule 913.h.(4) operator shall submit Form 27 Supplemental requesting closure of remediation within 30 days of conclusion of remediation activities if the area meets 915-1 standards. Date: 11/27/2023

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
The SMU 12-2-E location is under an open Remediation #24088 for Plugging and Abandonment of the well bore. At the time of inspection, the trench surrounding the well bore had recently been partially backfilled with new material. Operator shall assure soils in the remediation area are compliant with Table 915-1 standards.	sanchezcc	10/26/2023
Pit remediation for Pit ID 115231 Remediation # 28882 is ongoing at the time of inspection.	sanchezcc	10/26/2023
Operator shall adhere to Rule 911.c.(3) for Liner Disposal		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403574833	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6300257
710500065	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6300249