

Interim & Stormwater Inspection

September 20, 2023

Operator: Phoenix Resources # 10691

Location ID: 320668

Inspection Document # 709400569

Arapahoe County, CO

SWSW, 35 5S 65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
**Location Name: State 35-13 Well &
Tank Battery**
Location ID: 320668



Photo 1. Photo of location sign on site.



Photo 2. Photo of Tank battery and weeds (kochia & russian thistle) . Photo taken facing northeast.

Inspection Photos

Location Name: State 35-13 Well &

Tank Battery

Location ID: 320668



Photo 3. Photo of weeds (kochia & russian thistle) around equipment on tank battery pad. Photo taken facing North



Photo 4. Photo of gulying from stormwater near bunner on tank battery pad. Photo taken facing northwest.

Inspection Photos
Location Name: State 35-13 Well &
Tank Battery
Location ID: 320668



Photo 5. Photo of weeds (kosha & russian thistle) and erosion around burner on tank battery. Photo taken facing northwest.



Photo 6. Photo of Wellhead and tank battery. Photo taken facing south east.

Inspection Photos
Location Name: State 35-13 Well &
Tank Battery
Location ID: 320668



Photo 7. Photo of Wellhead and weeds (kochia & russian thistle) . Photo taken facing southwest.



Photo 8. Photo of Wellhead and weeds (kochia & russian thistle) . Photo taken facing northwest.

Inspection Photos
Location Name: State 35-13 Well &
Tank Battery
Location ID: 320668

Sep 20, 2023 at 1:43:56 PM
Aurora CO 80016
United States



Photo 9. Photo of Wellhead and weeds (kochia & russian thistle) among perennial grasses. Photo taken facing east.

Sep 20, 2023 at 1:44:05 PM
Aurora CO 80016
United States



Photo 10. Photo of weeds (kochia & russian thistle) among perennial grasses. Photo taken facing east.

Inspection Photos
Location Name: State 35-13 Well &
Tank Battery
Location ID: 320668

Sep 20, 2023 at 1:45:16 PM
Aurora CO 80016
United States



Photo 11. Photo taken of access road to wellhead, stormwater erosion causing deep gullying. Photo taken facing northeast.

Sep 20, 2023 at 1:47:57 PM
Aurora CO 80016
United States



Photo 12. Photo taken of undisturbed area for reference and vegetation comparison. Photo taken facing southeast.