

Inspection Photos

Loc: 320959

Operator: **PONCHO PRODUCTION COMPANY**

Inspection Date: 10/31/2023

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing southeast toward the abandoned well site.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:320959 | Date: 10/31/2023

Inspection Photos



Photo 2. Facing southeast toward the location. There is a water well and stock tank at the location belonging to the landowner. The 2 black tanks shown are associated equipment from the well site that must be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:320959 | Date: 10/31/2023

Inspection Photos



Photo 3. There are two tanks, pipe riser, meter run, and cement debris that remain. All equipment should have been removed within 3 months of well abandonment.



Inspection Photos



Photo 4. Facing southwest at the location. There are areas of the location with no vegetation growth which will need to be reclaimed. There is a yellow tank that remains at the southwest side of the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:320959 | Date: 10/31/2023

Inspection Photos



Photo 5. Facing southeast at the location. There are concrete debris scattered around the tanks.



Inspection Photos



Photo 6. Facing north toward the surrounding reference area which consists of native Blue grama, Sand drpseed, ect. There are abandoned pipe risers that remain 700 ft. northwest of the location.



Inspection Photos



Photo 7. There are abandoned pipe risers that remain 400 ft. north of the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:320959 | Date: 10/31/2023