

Final Reclamation Inspection

November 1st, 2023

Operator: BP American Production Company -
10000

Location ID: 385860

Inspection Document #: 714000100

La Plata County, CO

Township: NESE 15 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Pole Barn Monitor Well 1
Location ID: 385860



Photo 1. View of the project area taken from the center of the disturbance facing northeast.

Inspection Photos
Location Name: Pole Barn Monitor Well 1
Location ID: 385860



Photo 2. View of the northern interim reclamation area taken from the center facing northwest. Note: disturbance is dominated by kochia, tumble mustard and cheatgrass and does not appear consistent with adjacent reference area (see photo 4).

API #: 067-07969



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pole Barn Monitor Well 1
Location ID: 385860



Photo 3. Overview of the vegetation density within the project area.



Inspection Photos
Location Name: Pole Barn Monitor Well 1
Location ID: 385860



Photo 4. Reference area comprised of rabbitbrush and smooth brome.