

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403594226

Date Received:
11/13/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name

Phone

Email

Tyranny Bergin

970-313-5547

EHSCOGCCInspections@pdce.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 701900938

Inspection Date: 05/31/2023

FIR Submit Date: 06/29/2023

FIR Status:

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 323171

Location Name: NADINE-65N65W Number: 24NWNW County:

Qtrqr: NWN Sec: 24 Twp: 5N Range: 65W Meridian: 6
W

Latitude: 40.390145 Longitude: -104.618687

FACILITY - API Number: 05-123-00 Facility ID: 323171

Facility Name: NADINE-65N65W Number: 24NWNW

Qtrqr: NWN Sec: 24 Twp: 5N Range: 65W Meridian: 6
W

Latitude: 40.390145 Longitude: -104.618687

CORRECTIVE ACTIONS:

1 CA# 174225

Corrective Action: Comply with Rule 1002.f. Install or repair required BMPs per Rule 1002.f. BMP's shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to rule 1004.

Date: 05/31/2023

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 11/02/2023

Operator Comment: Satisfactory final reclamation inspection document #697504945 states "The tank battery location is superseded by the '34 Transportation Center', therefore, it is part of a land use change. CA complete.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Satisfactory final reclamation inspection document #697504945 states "The tank battery location is superseded by the '34 Transportation Center', therefore, it is part of a land use change. CA complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyranny Bergin

Signed: _____

Title: H&S Specialist-Operations

Date: 11/13/2023 8:40:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files