

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2023

Submitted Date:

12/07/2023

Document Number:

708301333**FIELD INSPECTION FORM**

Loc ID 335648	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 7 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																																																																							
<b>Operator Information:</b> OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>																																																																																																																											
<b>Contact Information:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>, CAERUS</td> <td></td> <td>COGCC.inspections@caerus oilandgas.com</td> <td></td> </tr> </table>				Contact Name	Phone	Email	Comment	, CAERUS		COGCC.inspections@caerus oilandgas.com		<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>																																																																																																															
Contact Name	Phone	Email	Comment																																																																																																																								
, CAERUS		COGCC.inspections@caerus oilandgas.com																																																																																																																									
<b>Inspected Facilities:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>283955</td><td>WELL</td><td>PR</td><td>09/01/2023</td><td>GW</td><td>045-12041</td><td>N. PARACHUTE WF11B K22 596</td><td>PR</td></tr> <tr><td>283956</td><td>WELL</td><td>PR</td><td>03/30/2008</td><td>GW</td><td>045-12040</td><td>N. PARACHUTE WF06B K22 596</td><td>PR</td></tr> <tr><td>283957</td><td>WELL</td><td>PR</td><td>03/07/2007</td><td>GW</td><td>045-12039</td><td>N. PARACHUTE WF05D K22 596</td><td>PR</td></tr> <tr><td>283958</td><td>WELL</td><td>PR</td><td>02/01/2011</td><td>GW</td><td>045-12038</td><td>N. PARACHUTE WF16B K22 596</td><td>PR</td></tr> <tr><td>283959</td><td>WELL</td><td>PR</td><td>03/07/2007</td><td>GW</td><td>045-12037</td><td>N. PARACHUTE WF05B K22 596</td><td>PR</td></tr> <tr><td>283960</td><td>WELL</td><td>PR</td><td>01/17/2008</td><td>GW</td><td>045-12026</td><td>N. PARACHUTE WF16B-21 K22 59</td><td>PR</td></tr> <tr><td>283961</td><td>WELL</td><td>PR</td><td>03/23/2006</td><td>GW</td><td>045-12027</td><td>N.PARACHUTE WF 12D K22 596</td><td>PR</td></tr> <tr><td>283962</td><td>WELL</td><td>PR</td><td>03/07/2007</td><td>GW</td><td>045-12028</td><td>N. PARACHUTE WF09D K22 596</td><td>PR</td></tr> <tr><td>283963</td><td>WELL</td><td>PR</td><td>03/23/2006</td><td>GW</td><td>045-12029</td><td>N.PARACHUTE WF 13B K22 596</td><td>PR</td></tr> <tr><td>283965</td><td>WELL</td><td>PR</td><td>03/07/2007</td><td>GW</td><td>045-12031</td><td>N. PARACHUTE WF14B K22 596</td><td>PR</td></tr> <tr><td>283966</td><td>WELL</td><td>PR</td><td>03/23/2006</td><td>GW</td><td>045-12032</td><td>N.PARACHUTE WF09B K22 596</td><td>PR</td></tr> <tr><td>283967</td><td>WELL</td><td>PR</td><td>03/07/2007</td><td>GW</td><td>045-12033</td><td>N. PARACHUTE WF15D K22 596</td><td>PR</td></tr> <tr><td>283968</td><td>WELL</td><td>PR</td><td>03/07/2007</td><td>GW</td><td>045-12034</td><td>N. PARACHUTE WF15B K22 596</td><td>PR</td></tr> <tr><td>283988</td><td>WELL</td><td>PR</td><td>11/22/2007</td><td>GW</td><td>045-12035</td><td>N. PARACHUTE WF12B K22 596</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	283955	WELL	PR	09/01/2023	GW	045-12041	N. PARACHUTE WF11B K22 596	PR	283956	WELL	PR	03/30/2008	GW	045-12040	N. PARACHUTE WF06B K22 596	PR	283957	WELL	PR	03/07/2007	GW	045-12039	N. PARACHUTE WF05D K22 596	PR	283958	WELL	PR	02/01/2011	GW	045-12038	N. PARACHUTE WF16B K22 596	PR	283959	WELL	PR	03/07/2007	GW	045-12037	N. PARACHUTE WF05B K22 596	PR	283960	WELL	PR	01/17/2008	GW	045-12026	N. PARACHUTE WF16B-21 K22 59	PR	283961	WELL	PR	03/23/2006	GW	045-12027	N.PARACHUTE WF 12D K22 596	PR	283962	WELL	PR	03/07/2007	GW	045-12028	N. PARACHUTE WF09D K22 596	PR	283963	WELL	PR	03/23/2006	GW	045-12029	N.PARACHUTE WF 13B K22 596	PR	283965	WELL	PR	03/07/2007	GW	045-12031	N. PARACHUTE WF14B K22 596	PR	283966	WELL	PR	03/23/2006	GW	045-12032	N.PARACHUTE WF09B K22 596	PR	283967	WELL	PR	03/07/2007	GW	045-12033	N. PARACHUTE WF15D K22 596	PR	283968	WELL	PR	03/07/2007	GW	045-12034	N. PARACHUTE WF15B K22 596	PR	283988	WELL	PR	11/22/2007	GW	045-12035	N. PARACHUTE WF12B K22 596	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																				
283955	WELL	PR	09/01/2023	GW	045-12041	N. PARACHUTE WF11B K22 596	PR																																																																																																																				
283956	WELL	PR	03/30/2008	GW	045-12040	N. PARACHUTE WF06B K22 596	PR																																																																																																																				
283957	WELL	PR	03/07/2007	GW	045-12039	N. PARACHUTE WF05D K22 596	PR																																																																																																																				
283958	WELL	PR	02/01/2011	GW	045-12038	N. PARACHUTE WF16B K22 596	PR																																																																																																																				
283959	WELL	PR	03/07/2007	GW	045-12037	N. PARACHUTE WF05B K22 596	PR																																																																																																																				
283960	WELL	PR	01/17/2008	GW	045-12026	N. PARACHUTE WF16B-21 K22 59	PR																																																																																																																				
283961	WELL	PR	03/23/2006	GW	045-12027	N.PARACHUTE WF 12D K22 596	PR																																																																																																																				
283962	WELL	PR	03/07/2007	GW	045-12028	N. PARACHUTE WF09D K22 596	PR																																																																																																																				
283963	WELL	PR	03/23/2006	GW	045-12029	N.PARACHUTE WF 13B K22 596	PR																																																																																																																				
283965	WELL	PR	03/07/2007	GW	045-12031	N. PARACHUTE WF14B K22 596	PR																																																																																																																				
283966	WELL	PR	03/23/2006	GW	045-12032	N.PARACHUTE WF09B K22 596	PR																																																																																																																				
283967	WELL	PR	03/07/2007	GW	045-12033	N. PARACHUTE WF15D K22 596	PR																																																																																																																				
283968	WELL	PR	03/07/2007	GW	045-12034	N. PARACHUTE WF15B K22 596	PR																																																																																																																				
283988	WELL	PR	11/22/2007	GW	045-12035	N. PARACHUTE WF12B K22 596	PR																																																																																																																				

283991	WELL	PR	02/01/2014	GW	045-12036	N. PARACHUTE WF11D K22 596	PR
414496	WELL	PR	02/16/2011	GW	045-18858	N. Parachute WF04A-27 K22 59	PR
414498	WELL	PR	07/08/2011	GW	045-18859	N. Parachute WF03D-27 K22 59	PR
414499	WELL	PR	09/14/2011	GW	045-18860	N. Parachute WF03C-27 K22 59	PR
414510	WELL	PR	09/14/2011	GW	045-18861	N. Parachute WF04B-22 K22 59	PR
414734	WELL	PR	10/10/2011	GW	045-18870	N. Parachute WF15A-22 K22 59	PR
414736	WELL	PR	09/14/2011	GW	045-18871	N. Parachute WF05D-22 K22 59	PR
414739	WELL	PR	07/07/2011	GW	045-18872	N. Parachute WF10A-21 K22 59	PR
414749	WELL	PR	07/13/2011	GW	045-18877	N. Parachute WF04B-27 K22 59	PR
414751	WELL	PR	10/10/2011	GW	045-18878	N. Parachute WF06C-22 K22 59	PR
414752	WELL	PR	09/14/2011	GW	045-18879	N. Parachute WF14D-22 K22 59	PR
414754	WELL	PR	10/10/2011	GW	045-18880	N. Parachute WF11A-22 K22 59	PR
414756	WELL	PR	06/17/2011	GW	045-18881	N. Parachute WF11D-22 K22 59	PR
414758	WELL	PR	04/13/2011	GW	045-18883	N. Parachute WF10D-21 K22 59	PR
414760	WELL	PR	01/24/2014	GW	045-18884	N. Parachute WF14C-22 K22 59	PR
414763	WELL	PR	09/09/2010	GW	045-18887	N. Parachute WF15A-21 K22 59	PR
414764	WELL	PR	05/12/2011	GW	045-18888	N. Parachute WF13D-22 K22 59	PR
414767	WELL	PR	06/17/2011	GW	045-18890	N. PARACHUTE WF03A-27 K22 59	PR
414768	WELL	PR	01/24/2014	GW	045-18891	N. Parachute WF12B-22 K22 59	PR
414769	WELL	PR	04/13/2011	GW	045-18892	N. Parachute WF13C-22 K22 59	PR
414772	WELL	PR	06/17/2011	GW	045-18895	N. Parachute WF04D-22 K22 59	PR
414774	WELL	PR	07/13/2011	GW	045-18896	N. Parachute WF09B-21 K22 59	PR
414777	WELL	PR	04/13/2011	GW	045-18897	N. PARACHUTE WF08D-21 K22 59	PR
414779	WELL	PR	09/14/2011	GW	045-18898	N. Parachute WF06B-22 K22 59	PR
414780	WELL	PR	07/13/2011	GW	045-18899	N. Parachute WF04C-27 K22 59	PR
414783	WELL	PR	06/17/2011	GW	045-18901	N. Parachute WF04C-22 K22 59	PR
414786	WELL	PR	09/07/2010	GW	045-18903	N. Parachute WF13B-22 K22 59	PR
414788	WELL	PR	09/08/2010	GW	045-18904	N. Parachute WF12C-22 K22 59	PR
414793	WELL	PR	04/13/2011	GW	045-18908	N. Parachute WF09D-21 K22 59	PR
414797	WELL	PR	09/14/2011	GW	045-18911	N. Parachute WF05C-22 K22 59	PR

414802	WELL	PR	09/14/2011	GW	045-18914	N. Parachute WF03B-27 K22 59	PR
414806	WELL	PR	05/12/2011	GW	045-18916	N. Parachute WF10B-21 K22 59	PR
414807	WELL	PR	09/14/2011	GW	045-18917	N. Parachute WF14B-22 K22 59	PR
414816	WELL	PR	07/01/2022	GW	045-18919	N. Parachute WF16A-21 K22 59	PR
414819	WELL	PR	06/01/2018	GW	045-18920	N. Parachute WF16C-21 K22 59	PR
414821	WELL	PR	07/29/2010	GW	045-18921	N. Parachute WF16D-21 K22 59	PR
414822	WELL	PR	10/10/2011	GW	045-18922	N. Parachute WF15C-22 K22 59	PR

**General Comment:**[COGCC Inspection Report Summary](#)

On 12/4/2023 at approximately 13:40, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, N. Parachute/WF K22 596 at Location ID #335648 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

1) No battery sign posted

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	No battery sign posted.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	01/06/2024
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970) 285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		

Comment: <a href="#">Mobile separator units</a>		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 20	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 20	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 20	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 20	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 20	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 11	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 11	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 10	
Comment: <a href="#">Chemical tanks</a>		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	250 bbls
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

Inspected Facilities									
Facility ID:	283955	Type:	WELL	API Number:	045-12041	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	283956	Type:	WELL	API Number:	045-12040	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	283957	Type:	WELL	API Number:	045-12039	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	283958	Type:	WELL	API Number:	045-12038	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	283959	Type:	WELL	API Number:	045-12037	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	283960	Type:	WELL	API Number:	045-12026	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	283961	Type:	WELL	API Number:	045-12027	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	283962	Type:	WELL	API Number:	045-12028	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			

Facility ID:	283963	Type:	WELL	API Number:	045-12029	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	283965	Type:	WELL	API Number:	045-12031	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	283966	Type:	WELL	API Number:	045-12032	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	283967	Type:	WELL	API Number:	045-12033	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	283968	Type:	WELL	API Number:	045-12034	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	283988	Type:	WELL	API Number:	045-12035	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	283991	Type:	WELL	API Number:	045-12036	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414496	Type:	WELL	API Number:	045-18858	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			



Facility ID:	414498	Type:	WELL	API Number:	045-18859	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:									Date:
Facility ID:	414499	Type:	WELL	API Number:	045-18860	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:									Date:
Facility ID:	414510	Type:	WELL	API Number:	045-18861	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:									Date:
Facility ID:	414734	Type:	WELL	API Number:	045-18870	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:									Date:
Facility ID:	414736	Type:	WELL	API Number:	045-18871	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:									Date:
Facility ID:	414739	Type:	WELL	API Number:	045-18872	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:									Date:
Facility ID:	414749	Type:	WELL	API Number:	045-18877	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:									Date:
Facility ID:	414751	Type:	WELL	API Number:	045-18878	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:									Date:

Facility ID:	414752	Type:	WELL	API Number:	045-18879	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414754	Type:	WELL	API Number:	045-18880	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414756	Type:	WELL	API Number:	045-18881	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414758	Type:	WELL	API Number:	045-18883	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414760	Type:	WELL	API Number:	045-18884	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414763	Type:	WELL	API Number:	045-18887	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414764	Type:	WELL	API Number:	045-18888	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414767	Type:	WELL	API Number:	045-18890	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			

Facility ID:	414768	Type:	WELL	API Number:	045-18891	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414769	Type:	WELL	API Number:	045-18892	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414772	Type:	WELL	API Number:	045-18895	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414774	Type:	WELL	API Number:	045-18896	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414777	Type:	WELL	API Number:	045-18897	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414779	Type:	WELL	API Number:	045-18898	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414780	Type:	WELL	API Number:	045-18899	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414783	Type:	WELL	API Number:	045-18901	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			

Facility ID:	414786	Type:	WELL	API Number:	045-18903	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414788	Type:	WELL	API Number:	045-18904	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414793	Type:	WELL	API Number:	045-18908	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414797	Type:	WELL	API Number:	045-18911	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414802	Type:	WELL	API Number:	045-18914	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414806	Type:	WELL	API Number:	045-18916	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414807	Type:	WELL	API Number:	045-18917	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			
Facility ID:	414816	Type:	WELL	API Number:	045-18919	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:						Date:			

Facility ID:	414819	Type:	WELL	API Number:	045-18920	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID:	414821	Type:	WELL	API Number:	045-18921	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID:	414822	Type:	WELL	API Number:	045-18922	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Culverts				
		Check Dams				
Berms						
		Sediment Traps				
		Ditches				
		Rip Rap				
				Material Handling And Spill Prevention		Chemical tanks in secondary containment
Compaction						
		Compaction				
		Berms				
		Gravel				
Seeding						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403618532	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6349418">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6349418</a>
708301334	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6349233">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6349233</a>