

Inspection Photos
Location Name: Wells Ranch USX AE 21-99HZ
Location ID: 415229



Photo 1 – Pumping Unit – Tumbleweeds



Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Wells Ranch USX AE 21-99HZ
Location ID: 415229



Photo 3 – Wellhead – Tumbleweeds



Photo 4 – Gas Engine and Propane Tank