

**Inspection Photos**  
**Location Name: Wells Ranch USX AE 19-14**  
**Location ID: 310008**



**Photo 1 – Wellhead Sign**



**Photo 2 –Wellhead**



**Inspection Photos**  
**Location Name: Wells Ranch USX AE 19-14**  
**Location ID: 310008**



**Photo 3 – Wellhead Tag**



**Photo 4 – Pumping Unit**

## Inspection Photos

Location Name: Wells Ranch USX AE 19-14

Location ID: 310008



**Photo 5 – Tumbleweed Debris and Unused Secondary Containment**