

Inspection Photos
Location Name: Boehner #3
Location ID: 323157



Photo 1: Location from entrance

Photo 2: Tank Battery

Inspection Photos
Location Name: Boehner #3
Location ID: 323157



Photo 3: Unmaintained berm

Photo 4: Unmaintained berm

Inspection Photos
Location Name: Boehner #3
Location ID: 323157




Photo 5: Unmaintained berm

Photo 6: Equipment, Debris

Inspection Photos
Location Name: Boehner #3
Location ID: 323157



Photo 7: Unmaintained berm

Photo 8: Unmaintained berm

Inspection Photos
Location Name: Boehner #3
Location ID: 323157




Photo 9: Unmaintained berm, Debris

Photo 10: Wellhead Sign

Inspection Photos
Location Name: Boehner #3
Location ID: 323157



Photo 11: Wellhead