

Final Reclamation Inspection

February 29th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 333535

Inspection Document #: 714000490

La Plata County, CO

Township: SENW 18 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-9 14
Location ID: 333535

2/29/24
+37.106610,-107.870927
314° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the disturbance facing center from the entrance. Note:
Logos location sign was not observed.

API #: 067-05423

Inspection Photos
Location Name: Bondad 33-9 14
Location ID: 333535

2/29/24
+37.106982,-107.870948
309° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of domestic tap on location.

API #: 067-05423

Inspection Photos
Location Name: Bondad 33-9 14
Location ID: 333535



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of weedy kochia debris observed around the Logos well head.

API #: 067-05423

Inspection Photos
Location Name: Bondad 33-9 14
Location ID: 333535

2/29/24
+37.106977,-107.871143
186° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of the western interim reclamation area facing south.

API #: 067-05423

Inspection Photos
Location Name: Bondad 33-9 14
Location ID: 333535



Photo 5. Reference area comprised of smooth brome and juniper.

