

# Final Reclamation Inspection

March 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326096

Inspection Document #: 714000558

La Plata County, CO

Township: NESE 33 33N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**


Department of Natural Resources



Inspection Photos  
Location Name: Cyrus Johnson A 1  
Location ID: 326096



Photo 1. Overview of the disturbance taken from the entrance facing center.



API #: 067-07465



Inspection Photos  
Location Name: Cyrus Johnson A 1  
Location ID: 326096



3/12/24  
+37.056724,-107.934184  
241° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the southern interim reclamation area facing south west. Vegetation is comprised of smooth brome, intermediate wheatgrass, sage brush and rabbit brush.

API #: 067-07465



Inspection Photos  
Location Name: Cyrus Johnson A 1  
Location ID: 326096



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Russian thistle debris observed in the northwest portion of the disturbance.

API #: 067-07465



Inspection Photos  
Location Name: Cyrus Johnson A 1  
Location ID: 326096



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area comprised of smooth brome, intermediate wheatgrass, crested wheatgrass, sage brush and rabbit brush.

API #: 067-07465