

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON K17 696

Location ID: 335596

Date: 3/15/2024



Location Entrance – Photo #09910



Wellheads – Photo #09916

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON K17 696

Location ID: 335596

Date: 3/15/2024



Separators – Photo #09917

Tank Battery – Photo #09911

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON K17 696

Location ID: 335596

Date: 3/15/2024



Inadequate Wildlife Protection – Photo #09913