

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/17NESW

Location ID: 335773

Date: 3/15/2024



Location Entrance – Photo #09927



Wellheads – Photo #09928

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/17NESW

Location ID: 335773

Date: 3/15/2024



Separators – Photo #09929



Tank Battery – Photo #09931

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/17NESW

Location ID: 335773

Date: 3/15/2024



Wildlife Entry Hazard – Photo #09930