

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/17SENW

Location ID: 335581

Date: 3/15/2024



Location Entrance – Photo #09933



Wellheads – Photo #09936

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/17SENW

Location ID: 335581

Date: 3/15/2024



Separators – Photo #09935



Tank Battery – Photo #09934

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/17SENW

Location ID: 335581

Date: 3/15/2024



Lack of Stabilization – Photo #09937



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09938**