

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Parachute Creek/5A

Location ID: 335781

Date: 3/15/2024



Location Entrance – Photo #09940



Wellheads – Photo #09947

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Parachute Creek/5A

Location ID: 335781

Date: 3/15/2024



Mar 15, 2024 at 13:11:17



Mar 15, 2024 at 13:13:12

Wellheads – Photo #09941

Separators – Photo #09946

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Parachute Creek/5A

Location ID: 335781

Date: 3/15/2024



Tank Battery – Photo #09942



FV Within 75' of Tank – Photo #09945

Inspection Photos


Location Name: CAERUS PICEANCE LLC, Parachute Creek/5A

Location ID: 335781

Date: 3/15/2024



Lack of Stabilization – Photo #09947



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09949**