

Briggsdale, CO Taproot – Hale site – Produced Water Release

Photo: 1

Description:

Initial site conditions.



Photo: 2

Description:

Initial site conditions.



Photo: 3

Description:

Hydro Excavation.
Daylighting pipeline.



Photo: 4

Description:

Hydro Excavation.



Briggsdale, CO Taproot – Hale site – Produced Water Release

Photo: 5

Description:

Loading impacted soil.

