

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC WATSON RANCH B Pad**  
**Location ID: 440705**



**Location Overview: Location is within High  
Priority/Density/Black Bear Habitat areas & in close proximity  
to NSO Habitat area. Location is within Rule 411a Surface  
Water Internal Buffer.**

**Section/Township/Range: 17 7S95W**





**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC WATSON RANCH B Pad**  
**Location ID: 440705**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC WATSON RANCH B Pad**  
**Location ID: 440705**



**Photo # 1653 Failure to maintain chemical BMP/chemical containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill.**



**Photo # 1654 Failure to maintain chemical BMP/chemical containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill.**