

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WATSON RANCH B Pad

Location ID: 440705



Mar 27, 2024 at 12:51:21 PM  
CO

Photo # 1640 From entrance to location



Mar 27, 2024 at 12:51:25 PM  
CO

Photo # 1641 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WATSON RANCH B Pad

Location ID: 440705



Photo # 1642 Location



Photo # 1643 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WATSON RANCH B Pad

Location ID: 440705



Photo # 1644 Location



Photo # 1645 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WATSON RANCH B Pad

Location ID: 440705



Photo # 1646 Location



Photo # 1647 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WATSON RANCH B Pad

Location ID: 440705



Photo # 1648 Location




Photo # 1649 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WATSON RANCH B Pad

Location ID: 440705



**Photo # 1650 Cellar not properly covered/wildlife & personnel hazard**



**Photo # 1651 Cellar not properly covered/wildlife & personnel hazard**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WATSON RANCH B Pad

Location ID: 440705



**Photo # 1652 Cellar not properly covered/wildlife & personnel hazard**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources