

# Inspection Photos

Loc: 308844

Operator: OGRIS OPERATING LLC

Inspection Date: 4/18/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:308844 | Date: 4/18/2024



## Inspection Photos



**Photo 1.** The equipment is fenced with cattle panels.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:308844 | Date: 4/18/2024