

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403767596

Date Received:
04/24/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

. General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000491

Inspection Date: 02/29/2024

FIR Submit Date: 03/11/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333535

Location Name: BONDAD 33-9-N33N9W Number: 18SEnw County: _____

Qtrqr: SEnw Sec: 18 Twp: 33N Range: 9W Meridian: N

Latitude: 37.106880 Longitude: -107.871120

FACILITY - API Number: 05-067-00

Facility ID: 333535

Facility Name: BONDAD 33-9-N33N9W Number: 18SEnw

Qtrqr: SEnw Sec: 18 Twp: 33N Range: 9W Meridian: N

Latitude: 37.106880 Longitude: -107.871120

CORRECTIVE ACTIONS:

1 CA# 192915

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002.

Date: 03/16/2024

Response: CA COMPLETED

Date of Completion: 04/23/2024

Operator Comment: Equipment repaired and stain cleaned and removed.

ECMC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an

ECMC Representative: acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

2 CA# 192916

Corrective Action: Comply with rule 605. Install or repair sign.

Date: 04/10/2024

Response: CA COMPLETED

Date of Completion: 04/23/2024

Operator Comment: Produced water tank sign repaired.

ECMC Decision: Approved via an AMI

ECMC Representative: Per photo included in attachment provided by operator the sign has been installed.

OPERATOR COMMENT AND SUBMITTAL

Comment: CA completed. See attached completion photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Gabby Riley Signed: _____

Title: Permitting Specialist I Date: 4/24/2024 10:36:48 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403767596	FIR RESOLUTION SUBMITTED
403767602	Alva Short B1; CA completion photos

Total Attach: 2 Files